General Environmental Incident Summary

Incident: 4043 Date/Time Notice: 3/17/2016 1330 DEM Incident No:

Responsible Party: WBI Energy Transmission Inc.

Date Incident: 3/17/2016 Time Incident: 1030 Duration: 2 minutes

County: McKenzie Twp: 153 Rng: 101 Sec: 20 Qtr: SE

Lat: 48.05797 Long: -103.69590 Method: Interpolation from map

Location Description: 7 Miles south of Williston on HWY #85, then 1/2 mile west on 45th street.

Spill occurred within the right of way of a natural gas pipeline construction

project.

Submitted By: Greg Huncovsky Affiliation:

Address: 2010 Montana Ave.

City: Glendive State: MT Zip:

Received By:

Contact Person: Greg Huncovsky

2010 Monana Ave. Glendive, MT 59330

Distance Nearest Occupied Building: 1 Miles Release Contained: Yes

Type of Incident: Ruptured hydraulic line on a Caterpillar Loader

Description of Released Contaminant: Hydraulic Fluid

Volume Spilled: 0.25 gallons Ag Related: No EPA Extremely Hazardous Substance: No Reported to NRC: No

Cause of Incident:

Hydraulic line ruptured on a Caterpillar loader.

Risk Evaluation:

None

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

Contaminated soil was promptly removed and bagged for disposal. Further environmental impacts are very unlikely.

Action Taken or Planned:

Spill was absorbed with pads and the contaminated soil was placed in a bag. The loader was also wiped clean with oil absorbing pads.

Wastes Disposal Location: IHD Solids Management, LLC landfill. (previously operated as Indian

Hills Disposal, Inc)

Agencies Involved:

Friday, January 27, 2017 Page 1 of 2

Updates

Date: 3/17/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, .25 gallon of hydraulic fluid was released along the right-of-way of Highway 85. More follow-up needed.

Date: 4/21/2016 Status: Inspection Author: O'Gorman, Brian

Updated Volume:

Notes:

Arrived at GPS location at 18:15. 70 degrees F, sunny, light winds. GPS location was along the fenceline south of 45th Street. Did not observe any disturbed soils or petroleum impacts. Drove east to an area where excavation equipment was sitting and a pipeline right-of-way (ROW) had recently been refilled and landscaped to the original shape. Walked the ROW area and did not notice any petroleum-stained soils. No further follow-up needed at this time.

Friday, January 27, 2017 Page 2 of 2